

# SPARE PARTS BULLETIN

April 2021

To: All Staff and Customers (One Stop Shop)  
From: Temperzone Product Manager

Subject: **Capacitor Change**

Part No. 012-001-087 to 012-001-089,  
012-001-114 to 012-001-129

Size: 3 $\mu$ Fd to 80  $\mu$ Fd


Effects: ALL MODELS

## Reason for Change

Higher temperature specification

## Note

- New capacitors come with soldered terminals, metal cap and a 200mm fly lead
- The mounting stud is the same as item it replaces, ie M8 stud
- Terminal connectors 2 way push-in (001-002-144) are available to join old and new wires.



012-001-115 to supercede 012-000-138	(3 Mfd)
012-001-116 to supercede 012-000-146	(3.5 Mfd)
012-001-117 to supercede 012-000-120	(4 Mfd)
012-001-087 to supersede 012-000-124	(5 Mfd)
012-001-088 to supersede 012-000-121	(6 Mfd)
012-001-089 to supersede 012-000-127	(8 Mfd)
012-001-114 to supersede 012-000-122	(10 Mfd)
012-001-118 to supersede 012-000-137	(12 Mfd)
012-001-119 to supersede 012-000-123	(15 Mfd)
012-001-120 to supersede 012-000-125	(18 Mfd)
012-001-121 to supersede 012-000-151	(22.5 Mfd)
012-001-122 to supersede 012-000-129	(30 Mfd)
012-001-123 to supersede 012-000-148	(35 Mfd)
012-001-124 to supersede 012-000-147	(40 Mfd)
012-001-125 to supersede 012-000-149	(45 Mfd)
012-001-126 to supersede 012-000-133	(50 Mfd)
012-001-127 to supersede 012-000-134	(55 Mfd)
012-001-128 to supersede 012-000-150	(60 Mfd)
012-001-129 to supersede 012-000-152	(80 Mfd)